

00684.003324.1



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
AKIRA UNNO ET AL.) : Examiner: M. Lebentritt
Appln. No.: 10/694,053) : Group Art Unit: 2824
Filed: October 28, 2003) : U.S. Patent No.: 6,841,490 B2
For: SEMICONDUCTOR SUBSTRATE, SOI) : Issued: January 11, 2005
SUBSTRATE AND MANUFACTURING) : August 22, 2005
METHOD THEREFOR)

Certificate
AUG 26 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

ATTENTION: CERTIFICATES OF CORRECTION BRANCH

**REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/23/2005 SSITHIB1 00000010 6841490


01 FC:1811

100.00 OP

AUG 26 2005

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Douglas W. Pinsky
Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DWP/lip/gmc

DC_MAIN 200280v1

AUG 26 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,841,490 B2

DATED : January 11, 2005

INVENTOR(S) : Akira Unno et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 5, "layer" should read --layers--.

Line 44, "not" should be deleted.

COLUMN 4

Line 35, "changes" should read --change--.

Line 37, "which" should read --with reference to--.

COLUMN 5

Line 31, "as to" should read --of--.

Line 51, "Is" should read --is--.

COLUMN 6

Line 3, "hearing" should read --heating--.

Line 30, "latm" should read --1 atm--.

Line 43, "is the film formation temperature)" should read --are the film formation temperatures)--.

COLUMN 7

Line 16, "has" should read --have--.

COLUMN 8

Line 31, "changes" should read --change--.

Table 3, "breakdwon" (both occurrences) should read --breakdown--, and
"accross" should read --across--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,841,490 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/lbp DC_MAIN 200285

→ _____
1 AUG 26 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,841,490 B2

DATED : January 11, 2005

INVENTOR(S) : Akira Unno et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 5, "layer" should read --layers--.

Line 44, "not" should be deleted.

COLUMN 4

Line 35, "changes" should read --change--.

Line 37, "which" should read --with reference to--.

COLUMN 5

Line 31, "as to" should read --of--.

Line 51, "Is" should read --is--.

COLUMN 6

Line 3, "hearing" should read --heating--.

Line 30, "latm" should read --1 atm--.

Line 43, "is the film formation temperature)" should read --are the film formation temperatures)--.

COLUMN 7

Line 16, "has" should read --have--.

COLUMN 8

Line 31, "changes" should read --change--.

Table 3, "breakdwon" (both occurrences) should read --breakdown--, and
"accross" should read --across--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,841,490 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWPLip DC_MAIN 200285

→ _____
AUG 26 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PATENT NO. : 6,841,490 B2
DATED : January 11, 2005
INVENTOR(S) : Akira Unno et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 2, "Zr" should read --Zr and--.

Table 5, "won" should read --own--, "accross"should read --across--, and
"breakdwon" should read --breakdown--.

COLUMN 10

Line 5, "reactiv" should read --reactive--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,841,490 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWPLip DC_MAIN 200285

→ _____

AUG 26 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,841,490 B2

DATED : January 11, 2005

INVENTOR(S) : Akira Unno et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 2, "Zr" should read --Zr and--.

Table 5, "won" should read --own--, "accross"should read --across--, and "breakdwon" should read --breakdown--.

COLUMN 10

Line 5, "reactiv" should read --reactive--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,841,490 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/lip DC_MAIN 200285

→ _____
AUG 26 2005